ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli

Street ID	Street Name	Significant Landmark
W0760, W0921, W0925, W0923, W0758, W0808, W0764	NA	Vigneshwara Layout Chikkasandra

Segment No.	Total Length (m)
12/C-W0760/S115922	318.28

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	64.86	77.510854	13.064168	77.511450	13.064126	W0921	W0921
2	107.29	77.511497	13.064668	77.511433	13.063700	W0923	W0923
3	85.99	77.511180	13.064469	77.511126	13.063694	W0925	W0925
4	60.14	77.510841	13.064137	77.510828	13.063593	W0760	W0760

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Restoration of Road cut portion done by BWSSB to Chikkasandra Village Government School surrounding area in Ward no.12 Shettyhalli Sub Division PKG 02	9985000	2019

Year	Type of Work	Other Work Type
2018 - 2019	Others	

Tender	Work Details	Job No. / Work Code
Tender		012-19-000064

Work Order No.	Work Order Date	Period of Extention
EE/DD/WO/387/19-20	23/08/2020	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
13/01/2020	13/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Professional Global Infrastructure Pvt Ltd		6481235.00

Phone No.

E-Mail ID

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0760, W0921, W0925, W0923,

Scanned by CamScanner

Name

vigneshwara layout

Pipe Inspection Details

Any Other Information

Number of Trees

0

Remarks

Date of Inspection

chikkasandra area

02/12/2022

Category	Image	Photo Remark
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Scanned by CamScanner